

Oil Field Environmental Incident Summary

Incident: 20150213153424 **Date/Time of Notice:** 02/13/2015 15:34

Responsible Party: CRESCENT POINT ENERGY U.S. CORP.

Well Operator: CRESCENT POINT ENERGY U.S. CORP.

Well Name: CPEUSC DRESSLER 36-25-158N-100W

Field Name: DUBLIN

Well File #: 25055

Date Incident: 2/13/2015

Time Incident: 13:10

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 100

Sec: 36

Qtr:

Location Description:

Submitted By: Chris DelHierro

Received By:

Contact Person: Scott Van De Woestyne
555 17TH STREET, SUITE 1800
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/11/2016

Clean Up Concluded: 2/13/2015

Risk Evaluation:

None

Areal Extent:

100' x 150'

Potential Environmental Impacts:

none

Action Taken or Planned:

HHL switch is being repaired/replaced

Wastes Disposal Location: Only surface snow was impacted. Material has been scraped and will be hauled to an authorized landfill

Agencies Involved:

Updates

Date: 2/13/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater popoff, sprayed off location. Surface snow was impacted. Followup is necessary.

Date: 2/18/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

13:19 The weather is clear, 10 °F with wind from the west at 0-5 mph. There is a workover rig at the site. Straight east of the flare, the stubble and snow has been scraped up and removed. The area goes east to a rock pile. There was no pooled oil; however, there are a couple of stained snow areas. The ground is frozen. There is also a cultivated area around the north side of pad. More followup needed. 48 27.555; -103 32.756

Date: 6/19/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Inspected East of pad to rock pile. Field has been planted and crop is coming in. Walked field between pad and rock pile, saw no stained areas, or areas of decreased plant growth.